Nease: 25A-RDP82-00457R00740053000 Sanitized - Approved F

L'INTELLIGENCE AGENCY

REPORT NO.

25X1A

Harris

MATION REPORT

CD NO.

COUNTRY USSR (Gorki Oblast)

DATE DISTR.

28 Jan. 1952

25X1X

Gorki/Sormovo Airfield and Aircraft Plant No. 21

NO. OF PAGES

25X1A

NO. OF ENCLS.

DATE OF INFO.

REPORT NO.

SUPPLEMENT TO

Winter 1947/1948 to October 1949

1. Location:

Southwestern edge of Gorki (56-19N, 43-51E).

- 2. No details on plant layout available. Work was definitely done in three shifts.
- 3. Factory field west of Flant 21 (see Annex)
 - a. Size about 1,500 x 1,000 meters.

Circular taxiway 5 meters wide. Two E-W runways each about 500 meters long and 30 meters wide. Aircraft dispersal areas with some aircraft revetments on the eastern and southern sides of the field.

Work was being done at the taxiway and runways,

Aircraft:

The maximum number of aircraft seen at the field at any given time was four or five jet fighters and 10 to 12 piston-powered fighters.

Obstacle and boundary lights were available.

4. Flying:

STATE

There was irregular flying with individual aircraft. Work was being done on the parked aircraft all day long.

Jet fighters;

Up to April 1949 one jet plane was seen flying every day. From this time there were usually two or three aircraft aloft,

SEE REVERSE FOR DECLASSIFICATION ACTION CLASSIFICATION VEN DISTRIBUTION NAVY X NSRB

	ADSO	×	STC FDP				DISTRIBUTION				MG1-4592
DS G	DADSO	1	STD		FDR		FD₩		СОММО		
RS:	B STA	x	Sanitize	be	FOS	νX	FFor Re	عا	AS CIV	¥	530001-5
bb	1278		FDM	X	FOT		TGS	×	OAD		

Sanitized - Approved For Release: CIA-RDP82-00457R007400530001-5

25X1C

SECRET/CONTROL

25X1A

CENTRAL INTELLIGENCE AGENCY

Flying was stopped at night, in rainy and hazy weather, during snowfalls and heavy wind. The planes were aloft for about one hour, often even longer. Ground take-off run about 600 meters, then followed a very steep climb to an attitude of 2,000 to 2,500 meters. The gliding approach was performed in a straight line from an altitude of 1,000 meters and a distance of about 1,500 meters. Length of landing run much shorter than take-off run.

Thile the jet fighters were readied for their take-off a small cart was parked beside them. Fellow-Pws stated that this was a preheater or a starter motor.

b. Conventional fighters:

Except in heavy rain and snowfall there was almost daily flying with conventional fighters, also at night. Duration of flight: 2 hours and more. Freheating during the winter: 20 to 30 minutes.

5. Description of the observed aircraft:

s. Jet fighter:

(1) Type I seen up to march 1949.

Jet engine in fuselage, nose wheel, pronounced sweep—back, angular wings with rounded tips. Id-wing or semi-high-wing monoplane, flat cockpit set at about leading edge of wing. Elevator assembly set high at rudder assembly. The entire tail assembly looked as if mounted on some sort of stick slightly-above the tail. Armament was not observed. A glittering tube about 40 centimeters long and projecting to the fore was particularly noted on the left—hand side of the fuselage.

(2) Type II, a slight modification of type I, was observed since March 1949. The wings had a more pronounced sweep-back and showed a bend to the rear in the last third. Lings had a slight dihedral and the rudder assembly was higher. Type II also had a greater speed and maneuverability than type I.

b. liston-powered fighters:

Stendard fighter type fitted with radial engine and tail wheel. Expert I'ms compared this type with the FW-190 and the Le-5.

6. Fuel supply:

There was a ripe line from a fuel depot on the Oka River to the airfield.

7. Security measures:

The plant and the factory field were surrounded by a barbed-wire fence. Sentries were on duty at day and patrols watched the installations at night.

Searchlights placed on the roofs of workshops illuminated the runway.

THE STATE OF THE S

No AAA emplacements and no camouflege were observed.

SECRET/CONTROL

SECRET/CONTROL

CENTRAL INTELLIGENCE AGENCY

25X1A

8. Rumors:

Two German engineers serving as test pilots were said to be employed in the plant.

9. A strikingly large number of groups composed of high-ranking officers inspected the plant in the Summer of 1949.

10. Rate of roduction:

The output of the plant was often discussed in the camp. The general estimate was:

a. Since March 1949 two jet fighters per day.

b. Conventional aircraft are not produced. Source supported this assumption by pointing out that, contrary to the jet fighters, the conventional fighters flew very irregularly and sometimes in formations of 9 or 10 planes.

25X1A Comment:

a. The data on the aircraft plant and the factory field are rather scanty. The estimated length of the runway (500 meters) is incorrect, as an aerial photograph shows the runway to actually be 1,200 meters long. This rectification is important in view of the length of the take-off and landing runs stated in para has

Attachment: Sketch of Gorki/Sormovo Airfield

SECRET/CONTROL 25X1